ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

 Client ID:
 M08095

 Date Received:
 12/08/11

 Date Extracted:
 12/13/11

 Date Analyzed:
 12/13/11

 Matrix:
 Water

 Units:
 ug/L (ppb)

Client: Alaskan Copper Works Project: M08095, F&BI 112115 Lab ID: 112115-01 x10

Data File: 112115-01 x10.052 Instrument: ICPMS1 Operator: AP

Concentration
Analyte: ug/L (ppb)

Chromium 516
Nickel 484
Copper 354
Zinc 26.0

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank Alaskan Copper Works Date Received: Not Applicable Project: M08095, F&BI 112115 Date Extracted: 12/13/11 Lab ID: I1-835 mb I1-835 mb.045 Date Analyzed: 12/13/11 Data File: ICPMS1

Matrix: Water Instrument: ICPM Units: ug/L (ppb) Operator: AP

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 98 60 125

Concentration
ug/L (ppb)

Chromium
Nickel
Copper
Classian

ENVIRONMENTAL CHEMISTS

Date of Report: 12/15/11 Date Received: 12/08/11

Project: M08095, F&BI 112115

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 112156-02 (Matrix Spike)

	Reporting	Spike	Sample	Percent Recovery	Percent Recovery	Acceptance	RPD
Analyte	Units	Level	Result	MS	MSD	Criteria	(Limit 20)
Chromium	ug/L (ppb)	20	<1	100	100	67-132	0
Nickel	ug/L (ppb)	20	<1	96	94	73-119	2
Copper	ug/L (ppb)	20	13.1	99 b	97 b	50-144	2 b
Zinc	ug/L (ppb)	50	16.4	95 b	9 3 b	46 - 14 8	2 b

Laboratory Code: Laboratory Control Sample

	Percent										
	Reporting	Spike	Recovery	Acceptance							
Analyte	Units	Level	LCS	Criteria							
Chromium	ug/L (ppb)	20	102	66-135							
Nickel	ug/L (ppb)	20	96	67-134							
Copper	ug/L (ppb)	20	99	66-134							
Zinc	ug/L (ppb)	50	95	57-135							

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb Analyte present in the blank and the sample.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht Analysis performed outside the method or client-specified holding time requirement.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- ${\it jl}$ The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- $\,\mathrm{nm}$ The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve Estimated concentration calculated for an analyte response above the valid instrument calibration range. A dilution is required to obtain an accurate quantification of the analyte.
- vo The value reported fell outside the control limits established for this analyte.
- x The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

112115			SA	MPLE	CHA	IN OF C	US	TO.	DY	1	ME	٠,	2/0	8/	(/				H	TY	
The state of the state of					MPLE CHAIN OF CUSTODY ME 12/08/								Page # of TURNAROUND TIME								
Send Report To GREACO THOMPSON Company HALASKAN Coppen Lobeks Address 628 S. Howard &					PROJECT NAME/NO.						PO#				□ Standard (2 Weeks) DRUSH						
Address 628 S. Horon &				Metro Self monton moso95								ζ	Rush charges authorized by:								
City, State, ZIP State 48184				REMA	RKS	j								SAMPLE DISPOSAL Dispose after 30 days Return samples							
Phone # 206-571-60	33 Fax# 2	L-587-4	709									_	-0-24					with inst	ruction	ns	
							ANALYSES REQU									JESTED					
Sample ID	Lab ID	Date	Time	Samp	le Type	# of containers	TPH-Diesel	TPH-Gasoline	BTEX by 8021B	VOCs by 8260	SVOCs by 8270	HFS	Chew NEZ						Notes		
M08095	01	12/3/11	9:00 Am	H	0	l				1			7								
								_		4	1	4									
				1				_			_	4									
					V V			-		_	_	-						_			
								-	4	-	-	+									
										1	+	4								-	
								-	+	1	+	4						_		72	
				-			-	-	-	+	-	-	-								
									-		-	1	-					<u>.</u>			
Friedman & Bruya, Inc.		 SIGNATU	RE	1		PRINT	NAM	Æ.			7		CO	MPA	NY			DATE	TI	ME	
3012 16th Avenue West										Acel			-	18/11		SIA					
Seattle, WA 98119-2029	Received by May Court				Whan Phan Fe B					B	Ī			18/11	V	100					
Ph. (206) 285-8282	Relinquished by	70 == 100															77.				
Fax (206) 283-5044	Received by:																	-1			
FORMS\COC\COC.DOC	116		-									-	Se	mnl	PS 7/	eceiv	ed at	. 14	°C		

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

December 15, 2011

Gerald Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on December 8, 2011 from the M08095, F&BI 112115 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU1215R.DOC